


Solder Instruction

- 1. Cable should be prepared for soldering. The cable/wires must be pretinned.
- 2. Insert cable/wire into solder cup.
- 3. Operate the soldering iron at 350°C, 50 Watt max . and use a pencil tip.
- 4. Put tip to wire in solder cup.
- 5. After 1 second bring in solder.
- 6. Heat for 3 seconds longer. Do not heat contact more than 4 seconds in total.
- 7. Remove soldering iron.
- 8. Wait until solder gets rigid again.
- 9. Do not solder adjacent contacts consecutively, alternate position within the connector to minimize heat build up.

RECOMMENDED PANEL CUT-OUT



T DUT GmbH	HAND					tol	erance		scale: 3:1
C Gr									material: SEE SHEET 1
IED OR MAY NOT Y WITHC	B√							dim. in mm	
OPIEC ID MA RTY V OF CC	9						date	name	title:
E COPIED OR AND MAY NOT PARTY WITHOUT HT OF CONEC GMI	DRAWING					drawn	11.05.12	Henneboel	PANEL CUT-OUT
WING MAY NOT B CED IN ANY WAY, D ON TO A THIRD PERMISSION. IIP AND COPYRIGI	ALTER CAD DR					appd.	14.05.12	Fischer	D-SUB MALE 9pos. SOLDER CUP
						norm			with threaded lock and 4-40 UNC stud bolt
						d-old			dwg no: DIN-
							45 =		15K1A1042 Ash:
	NOT	а	Original						
THIS DRA REPRODU BE PASSE WRITTEN OWNERSH	00	rev.	description	date	name	•		71-7	part no: SEE SHEET 1

<u>Д</u>