

Silicon identification

This document applies to the part numbers of STM32F091xB/xC devices listed in [Table 1](#) and their silicon revisions shown in [Table 2](#).

[Section 1](#) gives a summary and [Section 2](#) a description of device limitations, with respect to the device datasheet and reference manual RM0091.

Table 1. Device summary

Reference	Part numbers
STM32F091xB	STM32F091CB, STM32F091RB, STM32F091VB
STM32F091xC	STM32F091CC, STM32F091RC, STM32F091VC

Table 2. Device identification⁽¹⁾

Reference	Revision code marked on the device ⁽²⁾
STM32F091xB/xC	'A'

1. The REV_ID bits in the DBGMCU_IDCODE register indicate the revision code of the device (see the reference manual for details on the revision code).
2. Refer to datasheet for details on how to identify the silicon revision code on different types of package.

Contents

1	Summary of device limitations	4
2	Description of device limitations	6
2.1	System	6
2.1.1	Wakeup sequence from Standby mode when using more than one wakeup source	6
2.2	USART	6
2.2.1	Start bit detected too soon when sampling for NACK signal from the smartcard	6
2.2.2	Break request can prevent the Transmission Complete flag (TC) from being set	7
2.2.3	nRTS is active while RE or UE = 0	7
2.2.4	Receiver timeout counter starting in case of 2 stops bit configuration	7
2.2.5	Last byte written in TDR might not be transmitted if TE is cleared just after writing in TDR	7
2.3	GPIO	8
2.3.1	GPIOx locking mechanism not working properly for GPIOx_OTYPER register	8
2.4	I2C	8
2.4.1	Wrong data sampling when data set-up time ($t_{SU;DAT}$) is shorter than one I2CCLK period	8
2.4.2	Spurious bus error detection in master mode	8
2.4.3	Wrong behavior in Stop mode when wakeup from Stop mode is disabled in I ² C	9
2.4.4	10-bit master mode: new transfer cannot be launched if first part of the address has not been acknowledged by the slave	9
2.5	SPI	10
2.5.1	BSY bit may stay high when SPI is disabled	10
2.5.2	BSY bit may stay high at the end of a data transfer in slave mode	10
2.5.3	Wrong CRC transmitted in master mode with delayed SCK feedback	11
2.5.4	CRC error in SPI slave mode if internal NSS changes before CRC transfer	11
2.5.5	In I ² S slave mode: WS level must be set by the external master when enabling the I2S	11
2.6	RTC	12
2.6.1	Spurious tamper detection when disabling the tamper channel	12
2.6.2	A tamper event preceding the tamper detect enable not detected	12

2.6.3	RTC calendar registers are not locked properly	12
2.7	ADC	13
2.7.1	Overrun flag not set if EOC reset coincides with new conversion end	13
2.7.2	ADEN bit cannot be set immediately after the ADC calibration	13
2.8	CEC	13
2.8.1	Transmission blocked when transmitted start bit is corrupted	13
2.9	TSC	14
2.9.1	Inhibited acquisition in short transfer phase configuration	14
2.10	bxCAN	15
2.10.1	bxCAN time-triggered communication mode not supported	15
2.11	IWDG	15
2.11.1	RVU, PVU and WVU flags are not reset in STOP mode	15
2.11.2	RVU, PVU and WVU flags are not reset with low-frequency APB	15
3	Revision history	16

1 Summary of device limitations

The following table gives a quick references to all documented device limitations of STM32F091xB/xC and their status:

- A = workaround available
- N = no workaround available
- P = partial workaround available
- “-” grayed = limitation not existing / limitation fixed

Table 3. Summary of device limitations

Function	Section	Limitation	Status
			Rev. 'A'
System	2.1.1	Wakeup sequence from Standby mode when using more than one wakeup source	A
USART	2.2.1	Start bit detected too soon when sampling for NACK signal from the smartcard	N
	2.2.2	Break request can prevent the Transmission Complete flag (TC) from being set	A
	2.2.3	nRTS is active while RE or UE = 0	A
	2.2.4	Receiver timeout counter starting in case of 2 stops bit configuration	A
	2.2.5	Last byte written in TDR might not be transmitted if TE is cleared just after writing in TDR	A
GPIO	2.3.1	GPIOx locking mechanism not working properly for GPIOx_OTYPER register	P
I2C	2.4.1	Wrong data sampling when data set-up time (tSU;DAT) is shorter than one I2CCLK period	P
	2.4.2	Spurious bus error detection in master mode	A
	2.4.3	Wrong behavior in Stop mode when wakeup from Stop mode is disabled in I2C	A
	2.4.4	10-bit master mode: new transfer cannot be launched if first part of the address has not been acknowledged by the slave	A
SPI	2.5.1	BSY bit may stay high when SPI is disabled	A
	2.5.2	BSY bit may stay high at the end of a data transfer in slave mode	A
	2.5.3	Wrong CRC transmitted in master mode with delayed SCK feedback	A
	2.5.4	CRC error in SPI slave mode if internal NSS changes before CRC transfer	A
	2.5.5	In I2S slave mode: WS level must be set by the external master when enabling the I2S	A



Table 3. Summary of device limitations (continued)

Function	Section	Limitation	Status
			Rev. 'A'
RTC	2.6.1	<i>Spurious tamper detection when disabling the tamper channel</i>	P
	2.6.2	<i>A tamper event preceding the tamper detect enable not detected</i>	A
	2.6.3	<i>RTC calendar registers are not locked properly</i>	A
ADC	2.7.1	<i>Overrun flag not set if EOC reset coincides with new conversion end</i>	A
	2.7.2	<i>ADEN bit cannot be set immediately after the ADC calibration</i>	A
CEC	2.8.1	<i>Transmission blocked when transmitted start bit is corrupted</i>	P
TSC	2.9.1	<i>Inhibited acquisition in short transfer phase configuration</i>	P
bxCAN	2.10.1	<i>bxCAN time-triggered communication mode not supported</i>	N
IWDG	2.11.1	<i>RVU, PVU and WVU flags are not reset in STOP mode</i>	A
	2.11.2	<i>RVU, PVU and WVU flags are not reset with low-frequency APB</i>	N

2 Description of device limitations

The following sections describe device limitations and provide workarounds if available. They are grouped by device functions.

2.1 System

2.1.1 Wakeup sequence from Standby mode when using more than one wakeup source

Description

The various wakeup sources are logically OR-ed in front of the rising-edge detector which generates the wakeup flag (WUF). The WUF needs to be cleared prior to Standby mode entry, otherwise the MCU wakes up immediately.

If one of the configured wakeup sources is kept high during the clearing of the WUF (by setting the CWUF bit), it may mask further wakeup events on the input of the edge detector. As a consequence, the MCU might not be able to wake up from Standby mode.

Workaround

To avoid this problem, the following sequence should be applied before entering Standby mode:

- Disable all used wakeup sources,
- Clear all related wakeup flags,
- Re-enable all used wakeup sources,
- Enter Standby mode

Note: *Be aware that, when applying this workaround, if one of the wakeup sources is still kept high, the MCU will enter Standby mode but then it wakes up immediately generating a power reset.*

2.2 USART

2.2.1 Start bit detected too soon when sampling for NACK signal from the smartcard

Description

In the ISO7816, when a character parity error is incorrect, the smartcard receiver shall transmit a NACK error signal at (10.5 ± 0.2) etu after the character START bit falling edge. In this case, the USART transmitter should be able to detect correctly the NACK signal by sampling at (11.0 ± 0.2) etu after the character START bit falling edge.

The USART peripheral used in smartcard mode doesn't respect the (11 ± 0.2) etu timing, and when the NACK falling edge arrives at 10.68 etu or later, the USART might misinterpret this transition as a START bit even if the NACK is correctly detected.

Workaround

None

2.2.2 Break request can prevent the Transmission Complete flag (TC) from being set**Description**

After the end of transmission of a data (D1), the Transmission Complete (TC) flag will not be set in the following conditions:

- CTS hardware flow control is enabled.
- D1 is being transmitted.
- A break transfer is requested before the end of D1 transfer.
- nCTS is de-asserted before the end of transfer of D1.

Workaround

If the application needs to detect the end of transfer of the data, the break request should be done after making sure that the TC flag is set.

2.2.3 nRTS is active while RE or UE = 0**Description**

The nRTS line is driven low as soon as RTSE bit is set even if the USART is disabled (UE = 0 or the receiver is disabled (RE = 0) i.e. not ready to receive data.

Workaround

Configure the I/O used for nRTS as alternate function after setting the UE and RE bits.

2.2.4 Receiver timeout counter starting in case of 2 stops bit configuration**Description**

In the case of 2 stop bits configuration, the receiver timeout counter starts counting from the end of the second stop bit of the last character instead of the end of the first stop bit.

Workaround

Change the RTO value in the USARTx_RTOR register by subtracting 1 bit duration.

2.2.5 Last byte written in TDR might not be transmitted if TE is cleared just after writing in TDR**Description**

If the USART clock source is slow (for example LSE) and TE bit is cleared immediately after the last write to TDR, the last byte will probably not be transmitted.

Workarounds

1. Wait until TXE flag is set before clearing TE bit
2. Wait until TC flag is set before clearing TE bit

2.3 GPIO

2.3.1 GPIOx locking mechanism not working properly for GPIOx_OTYPER register

Description

Locking of GPIOx_OTYPER[i] with $i = 15..8$ depends from setting of GPIOx_LCKR[i-8] and not from GPIOx_LCKR[i]. GPIOx_LCKR[i-8] is locking GPIOx_OTYPER[i] together with GPIOx_OTYPER[i-8]. It is not possible to lock GPIOx_OTYPER[i] with $i = 15..8$, without locking also GPIOx_OTYPER[i-8].

Workaround

The only way to lock GPIOx_OTYPER[i] with $i=15..8$ is to lock also GPIOx_OTYPER[i-8].

2.4 I2C

2.4.1 Wrong data sampling when data set-up time ($t_{SU;DAT}$) is shorter than one I2CCLK period

Description

The I²C-bus specification and user manual specify a minimum data set-up time ($t_{SU;DAT}$) as:

- 250 ns in Standard mode
- 100 ns in Fast mode
- 50 ns in Fast mode Plus

The I²C-bus SDA line is not correctly sampled when $t_{SU;DAT}$ is smaller than one I2CCLK (I²C-bus peripheral clock) period: the previous SDA value is sampled instead of the current one. This can result in a wrong receipt of slave address, data byte, or acknowledge bit.

Workaround

Increase the I2CCLK frequency to get I2CCLK period within the transmitter minimum data set-up time. Alternatively, increase transmitter's minimum data set-up time.

2.4.2 Spurious bus error detection in master mode

Description

In master mode, a bus error can be detected by mistake, so the BERR flag can be wrongly raised in the status register. This will generate a spurious Bus Error interrupt if the interrupt is enabled. A bus error detection has no effect on the transfer in master mode, therefore the I2C transfer can continue normally.

Workaround

If a bus error interrupt is generated in master mode, the BERR flag must be cleared by software. No other action is required and the on-going transfer can be handled normally.

2.4.3 Wrong behavior in Stop mode when wakeup from Stop mode is disabled in I²C

Description

When wakeup from Stop mode is disabled in I²C (WUPEN = 0) and the MCU enters Stop mode while a transfer is on going on the bus, some wrong behaviors may happen:

1. BUSY flag can be wrongly set when the MCU exits Stop mode. This prevents from initiating a transfer in master mode, as the START condition cannot be sent when BUSY is set.
2. If clock stretching is enabled (NOSTRETCH = 0), the I²C clock SCL may be stretched low by the I²C as long as the MCU is in Stop mode. This limitation may occur when the Stop mode is entered during the address phase of a transfer on the I²C bus while SCL = 0. Therefore the transfer may be stalled as long as the MCU is in Stop mode. The probability of the occurrence depends also on the timings configuration, the peripheral clock frequency and the I²C bus frequency.

These behaviors can occur in Slave mode and in Master mode in a multi-master topology.

Workaround

Disable the I²C (PE=0) before entering Stop mode and re-enable it in Run mode.

2.4.4 10-bit master mode: new transfer cannot be launched if first part of the address has not been acknowledged by the slave

Description

In master mode, the master automatically sends a STOP bit when the slave has not acknowledged a byte during the address transmission.

In 10-bit addressing mode, if the first byte of the 10-bit address (5-bit header + 2 MSBs of the address + direction bit) has not been acknowledged by the slave, the STOP bit is sent but the START bit is not cleared and the master cannot launch a new transfer.

Workaround

When the I2C is configured in 10-bit addressing master mode and the NACKF status flag is set in the I2C_ISR register while the START bit is still set in I2C_CR2 register, then proceed as follows:

1. Wait for the STOP condition detection (STOPF = 1 in I2C_ISR register).
2. Disable the I2C peripheral.
3. Wait for a minimum of 3 APB cycles.
4. Enable the I2C peripheral again.

2.5 SPI

2.5.1 BSY bit may stay high when SPI is disabled

Description

The BSY flag may remain high upon disabling the SPI while operating in:

- a master transmit mode and the TXE flag is low (data register full).
- a master receive only mode (simplex receive or half-duplex bidirectional receive phase) and an SCK strobing edge has not occurred since the transition of the RXNE flag from low to high.
- slave mode and NSS signal is removed during the communication.

Workaround

When the SPI operates in:

- a master transmit mode, disable the SPI when TXE=1 and BSY=0.
- a master receive only mode, ignore the BSY flag.
- slave mode, do not remove the NSS signal during the communication.

2.5.2 BSY bit may stay high at the end of a data transfer in slave mode

Description

In slave mode, The BSY bit is not reliable to handle the end of data frame transaction due to some bad synchronization between the CPU clock and external SCK clock provided by the SPI master. Sporadically, the BSY bit is not cleared at the end of a data frame transfer. As a consequence, it is not recommended to rely on the BSY bit before entering low-power mode or modifying the SPI configuration (e.g. direction of the bidirectional mode).

Workaround

- When the SPI interface is in receive mode, the end of a transaction with the master can be detected by the corresponding RXNE event when this flag is set after the last bit of that transaction is sampled and the received data are stored.
- When the following sequence is used, the synchronization issue does not occur. The BSY bit works correctly and can be used to recognize the end of any transmission transaction (including when RXNE is not raised in bidirectional mode):
 - a) Write the last data into data register.
 - b) Poll the TXE flag till it becomes high to make sure the data transfer has started.
 - c) Disable the SPI interface by clearing the SPE bit while the last data transfer is on going.
 - d) Poll the BSY bit till it becomes low.

Note: The second workaround can be used only when the CPU is fast enough to disable the SPI interface after a TXE event is detected while the data frame transfer is ongoing. It cannot be implemented when the ratio between CPU and SPI clock is low and the data frame is particularly short. At this specific case, the timeout can be measured from the TXE event instead by calculating a fixed number of CPU clock cycles corresponding to the time necessary to complete the data frame transaction.

2.5.3 Wrong CRC transmitted in master mode with delayed SCK feedback

Description

In transmit transaction of the SPI/I²S interface in SPI master mode with CRC enabled, the CRC data transmission may be corrupted if the delay of an internal feedback signal derived from the SCK output (further feedback clock) is greater than one APB clock period. While data and CRC bit shifting and transfer is based on an internal clock, the CRC progressive calculation uses the feedback clock. If the delay of the feedback clock is greater than one APB period, the transmitted CRC value may get wrong.

The main factors contributing to the delay increase are low V_{DD} level, high temperature, high SCK pin capacitive load and low SCK IO output speed. The SPI communication speed has no impact.

Workaround

Set the application such as to speed up the SCK edges and / or slow down the APB clock, through:

- configuring the SCK output GPIO so as to reach lower output impedance
- minimizing the capacitive load on the SCK output line
- configuring the APB clock speed

2.5.4 CRC error in SPI slave mode if internal NSS changes before CRC transfer

Description

When the device is configured as SPI slave, the transition of the internal NSS after the CRCNEXT flag is set may result in wrong CRC value computed by the device and, as a consequence, a CRC error. As a consequence, the NSS pulse mode cannot be used along with the CRC function.

Workaround

Prevent the internal NSS signal from changing in the critical period, by configuring the device to software NSS control if the SPI master pulses the NSS (for example in NSS pulse mode).

2.5.5 In I²S slave mode: WS level must be set by the external master when enabling the I2S

Description

In slave mode, the WS signal level is used only to start the communication. If the I2S (in slave mode) is enabled while the master is already sending the clock and the WS signal level is low (for I²S protocol) or is high (for the LSB or MSB-justified mode), the slave starts communicating data immediately. In this case, the master and slave will be desynchronized throughout the whole communication.

Workaround

The I2S peripheral must be enabled when the external master sets the WS line at:

- High level when the I²S protocol is selected.
- Low level when the LSB or MSB-justified mode is selected.

2.6 RTC**2.6.1 Spurious tamper detection when disabling the tamper channel****Description**

If the tamper detection is configured for detecting on falling-edge event (TAMPFLT[1:0]=00 and TAMPxTRG=1) and if the tamper event detection is disabled when the tamper pin is at high level, a false detection of a tamper event occurs, which may result in the erasure of backup registers.

Workaround

The false detection of tamper event cannot be avoided. The erasure of the backup registers can be avoided by setting the TAMPxNOERASE bit before clearing the TAMPxE bit, in two separate RTC_TAMPCR write accesses.

2.6.2 A tamper event preceding the tamper detect enable not detected**Description**

When the tamper detect is enabled, set in edge detection mode (TAMPFLT[1:0]=00), and

- set to active rising edge (TAMPxTRG=0): if the tamper input is already high (tamper event already occurred) at the moment of enabling the tamper detection, the tamper event may not be detected. The probability of detection increases with the APB frequency.
- set to active falling edge (TAMPxTRG=1): if the tamper input is already low (tamper event already occurred) at the moment of enabling the tamper detection, the tamper event is not detected.

Workaround

The I/O state should be checked by software in the GPIO registers, after enabling the tamper detection and before writing sensitive values in the backup registers, in order to ensure that no active edge occurred before enabling the tamper event detection.

2.6.3 RTC calendar registers are not locked properly**Description**

When reading the calendar registers with BYPSHAD=0, the RTC_TR and RTC_DR registers may not be locked after the read of RTC_SSR register. This happens if the read of RTC_SSR is initiated one APB clock period before the shadow registers are updated. This can result in a non-consistency of the 3 registers. Similarly, RTC_DR register can be updated after the read of the RTC_TR register instead of being locked.

Workaround

1. Use BYPSHAD = 1 mode (Bypass shadow registers), or
2. In case BYPSHAD = 0: read SSR again after reading SSR/TR/DR to confirm that SSR is still the same, otherwise read the values again.

2.7 ADC**2.7.1 Overrun flag not set if EOC reset coincides with new conversion end****Description**

If the EOC flag is cleared by ADC_DR register read operation or by software during the same APB cycle in which the data from a new conversion are written in the ADC_DR register, the overrun event duly occurs (which results in the loss of either current or new data) but the overrun flag (OVR) may stay low.

Workaround

Clear the EOC flag through ADC_DR register read operation or by software within less than one ADC conversion cycle period from the last conversion cycle end, so as to avoid the coincidence with the new conversion cycle end.

2.7.2 ADEN bit cannot be set immediately after the ADC calibration**Description**

At the end of the ADC calibration, an internal reset of ADEN bit occurs four ADC clock cycles after the ADCAL bit is cleared by hardware. As a consequence, if the ADEN bit is set within those four ADC clock cycles, it is reset shortly after by the calibration logic and the ADC remains disabled.

Workaround

1. Keep setting the ADEN bit until the ADRDY flag goes high.
2. After the ADCAL is cleared, wait for a minimum of four ADC clock cycles before setting the ADEN bit.

2.8 CEC**2.8.1 Transmission blocked when transmitted start bit is corrupted****Description**

When the HDMI-CEC communication start bit transmitted by the device is corrupted by another device on the CEC line, the CEC transmission is stalled.

This failure is unlikely to happen as the CEC start bit corruption by another device can only occur if that device does not respect the CEC communication protocol.


The start bit timing standard tolerances are shown in [Figure 1](#). The start bit is initiated by the device by driving the CEC line low (reference point). After 3.7 ms, the device releases the

CEC line and starts checking its level. The following conditions must be met for the start bit to be valid:

- the CEC line goes high no later than 3.9 ms (4.05 ms with extended tolerance) from the reference point
- a falling edge on the CEC line does not occur earlier than 4.3 ms (4.15 ms with extended tolerance) from the reference point

If one of these conditions is not met, the transmission is aborted and never automatically retried. No error flag is set and the TXSOM (Tx Start Of Message) bit is not cleared.

Figure 1. HDMI-CEC start bit format with tolerances



Workaround

A way to work this limitation around is for the system-level CEC application software to start a time-out counter when setting TXSOM bit and stop it upon TXBR or TXEND event. In case of time-out, the HDMI-CEC functional block is disabled then enabled, by setting the CECEN bit in CEC_CR register to 0 then to 1. This clears the TXSOM bit.

2.9 TSC

2.9.1 Inhibited acquisition in short transfer phase configuration

Description

The GPIO input buffer is masked outside the transfer window time and then sampled twice before being checked for the acquisition. This check is performed on the last touch sensing clock cycle of the charge transfer phase. When the charge transfer duration is less than three clock cycles, the acquisition is inhibited.

Workaround

Do not use the following TSC control register configurations:

- PGPSC[2:0] bits set to 000 and CTPL[3:0] bits set to 0000 or 0001 in TSC_CR register
- PGPSC[2:0] bits set to 001 and bits CTPL[3:0] set to 0000 in TSC_CR register

2.10 bxCAN

2.10.1 bxCAN time-triggered communication mode not supported

Description

The time-triggered communication mode is not supported. As a consequence, timestamp values are not available. The TTCM bit in the CAN_MCR register must be kept at 0 (time-triggered communication mode disabled).

Workaround

None

2.11 IWDG

2.11.1 RVU, PVU and WVU flags are not reset in STOP mode

Description

The RVU, PVU and WVU flags of the IWDG_SR register are set by hardware after a write access to the IWDG_RLR and the IWDG_PR registers, respectively. If the Stop mode is entered immediately after the write access, the RVU, PVU and WVU flags are not reset by hardware. Before performing a second write operation to the IWDG_RLR or the IWDG_PR register, the application software must wait for the RVU, PVU and WVU flags to be reset. However, since the RVU/PVU/WPU bit is not reset after exiting the Stop mode, the software goes into an infinite loop and the independent watchdog (IWDG) generates a reset after the programmed timeout period.

Workaround

Wait until the RVU, PVU and WVU flags of the IWDG_SR register are reset, before entering the Stop mode.

2.11.2 RVU, PVU and WVU flags are not reset with low-frequency APB

Description

The RVU, PVU and WVU flags of the IWDG_SR register are set by hardware after a write access to the IWDG_RLR and the IWDG_PR registers, respectively. If the APB clock frequency is two times slower than the IWDG clock frequency, the RVU, PVU and WVU flags will never be reset by hardware.

Workaround

None

3 Revision history

Table 4. Document revision history

Date	Revision	Changes
12-Nov-2014	1	Initial release.
12-Oct-2016	2	<p>Added:</p> <p>USART:</p> <ul style="list-style-type: none"> – Section 2.2.1: Start bit detected too soon when sampling for NACK signal from the smartcard – Section 2.2.2: Break request can prevent the Transmission Complete flag (TC) from being set – Section 2.2.3: nRTS is active while RE or UE = 0 – Section 2.2.4: Receiver timeout counter starting in case of 2 stops bit configuration <p>I2C:</p> <ul style="list-style-type: none"> – Section 2.4.1: Wrong data sampling when data set-up time (tSU;DAT) is shorter than one I2CCLK period – Section 2.4.2: Spurious bus error detection in master mode – Section 2.4.4: 10-bit master mode: new transfer cannot be launched if first part of the address has not been acknowledged by the slave <p>SPI:</p> <ul style="list-style-type: none"> – Section 2.5.1: BSY bit may stay high when SPI is disabled – Section 2.5.2: BSY bit may stay high at the end of a data transfer in slave mode – Section 2.5.3: Wrong CRC transmitted in master mode with delayed SCK feedback – Section 2.5.4: CRC error in SPI slave mode if internal NSS changes before CRC transfer <p>RTC:</p> <ul style="list-style-type: none"> – Section 2.6.1: Spurious tamper detection when disabling the tamper channel – Section 2.6.2: A tamper event preceding the tamper detect enable not detected – Section 2.6.3: RTC calendar registers are not locked properly <p>ADC:</p> <ul style="list-style-type: none"> – Section 2.7.1: Overrun flag not set if EOC reset coincides with new conversion end – Section 2.7.2: ADEN bit cannot be set immediately after the ADC calibration

Table 4. Document revision history (continued)

Date	Revision	Changes
12-Oct-2016	2	<p><i>CEC:</i></p> <ul style="list-style-type: none"> – <i>Section 2.8.1: Transmission blocked when transmitted start bit is corrupted</i> <p><i>TSC:</i></p> <ul style="list-style-type: none"> – <i>Section 2.9.1: Inhibited acquisition in short transfer phase configuration</i> <p><i>bxCAN:</i></p> <ul style="list-style-type: none"> – <i>Section 2.10.1: bxCAN time-triggered communication mode not supported</i> <p><i>IWDG:</i></p> <ul style="list-style-type: none"> – <i>Section 2.11.1: RVU, PVU and WVU flags are not reset in STOP mode</i> – <i>Section 2.11.2: RVU, PVU and WVU flags are not reset with low-frequency APB</i> <p>Modified:</p> <ul style="list-style-type: none"> – Document structure – Cover page and <i>Table 3</i> organization

IMPORTANT NOTICE – PLEASE READ CAREFULLY

STMicroelectronics NV and its subsidiaries ("ST") reserve the right to make changes, corrections, enhancements, modifications, and improvements to ST products and/or to this document at any time without notice. Purchasers should obtain the latest relevant information on ST products before placing orders. ST products are sold pursuant to ST's terms and conditions of sale in place at the time of order acknowledgement.

Purchasers are solely responsible for the choice, selection, and use of ST products and ST assumes no liability for application assistance or the design of Purchasers' products.

No license, express or implied, to any intellectual property right is granted by ST herein.

Resale of ST products with provisions different from the information set forth herein shall void any warranty granted by ST for such product.

ST and the ST logo are trademarks of ST. All other product or service names are the property of their respective owners.

Information in this document supersedes and replaces information previously supplied in any prior versions of this document.

© 2016 STMicroelectronics – All rights reserved