

STM32L100x6/8/B, STM32L151x6/8/B and STM32L152x6/8/B ultra-low-power device limitations

Silicon identification

This errata sheet applies to the revisions Y, X, W and V of the STMicroelectronics STM32L100x6, STM32L100x8, STM32L100xB, STM32L15xx6, STM32L15xx8 and STM32L15xxB ultra-low-power products. This family features an ARM® 32-bit Cortex®-M3 core, for which an errata notice is also available (see [Section 1](#) for details).

A full list of root part numbers is shown in [Table 1](#).

The products can be identified (see [Table 2](#)) by:

- The revision code marked below the sales type on the device package
- The last three digits of the internal sales type printed on the box label

Table 1. Device summary

Reference	Part number
STM32L100x6/8/B	STM32L100RB, STM32L100R8, STM32L100C6
STM32L151x6/8/B	STM32L151CB, STM32L151RB, STM32L151VB, STM32L151R6, STM32L151C8, STM32L151R8, STM32L151V8, STM32L151C6
STM32L152x6/8/B	STM32L152CB, STM32L152RB, STM32L152VB, STM32L152R6, STM32L152C8, STM32L152R8, STM32L152V8, STM32L152C6

Table 2. Device identification⁽¹⁾

Sales type	Revision code ⁽²⁾ marked on device
STM32L100x6/8/B	“Y”, “X”, “W” and “V”
STM32L151x6/8/B	“Y”, “X”, “W” and “V”
STM32L152x6/8/B	“Y”, “X”, “W” and “V”

1. The REV_ID bits in the DBGMCU_IDCODE register show the revision code of the device (see the STM32L15xxx reference manual for details on how to find the revision code).
2. Refer to the device datasheets for details on how to identify the revision code on the different packages.

Caution: This errata sheet does not apply to:

- STM32L100C6-A
- STM32L100R8-A
- STM32L100RB-A

These are covered by a separate errata sheet.

Contents

1	ARM® 32-bit Cortex®-M3 limitations	6
1.1	Cortex®-M3 limitation description for the STM32L1xxxx ultra-low-power devices	6
1.1.1	Cortex®-M3 LDRD with base in list may result in incorrect base register when interrupted or faulted	6
1.1.2	Cortex®-M3 event register is not set by interrupts and debug	7
1.1.3	Cortex®-M3 interrupted loads to the stack-pointer can cause erroneous behavior	7
1.1.4	SVC and BusFault/MemManage may occur out of order	8
2	STM32L1xxx6/8/B device silicon limitations	9
2.1	System limitations	12
2.1.1	Unexpected Flash/EEPROM behavior on system reset during programming/erasing	12
2.1.2	Bootloader unavailability	12
2.1.3	Undefined instruction exception during IAP	12
2.1.4	Factory trimming values not available	13
2.1.5	Debug support for low-power modes with entry through the WFE instruction	13
2.1.6	Operating temperature range limited to “-10°C to +85°C”	14
2.1.7	MCU may not restart after a reset when using HSE bypass as main clock source	14
2.1.8	Pull-up on PB7 when configured in analog mode	14
2.1.9	Range 1 of dynamic voltage scaling has a limit lower than 2.0 V	14
2.1.10	HSEBYP bit of Clock control register has an undefined reset value	15
2.1.11	Delay after enabling an RCC peripheral clock	15
2.1.12	Flash memory wakeup issue when waking up from Stop or Sleep with Flash memory in power-down mode	15
2.1.13	Unexpected system reset when waking up from Stop mode with regulator in low-power mode	16
2.2	IWDG peripheral limitation	16
2.2.1	RVU and PVU flags are not reset in Stop mode	16
2.3	I ² C peripheral limitations	17
2.3.1	SMBus standard not fully supported	17
2.3.2	Wrong behavior of I ² C peripheral in Master mode after misplaced STOP	17

2.3.3	Violation of I ² C “setup time for repeated START condition” parameter	18
2.3.4	In I ² C slave “NOSTRETCH” mode, underrun errors may not be detected and may generate bus errors	18
2.3.5	Spurious bus error detection in Master mode	19
2.3.6	10-bit Master mode: new transfer cannot be launched if first part of the address has not been acknowledged by the slave	19
2.4	USART peripheral limitations	20
2.4.1	Idle frame is not detected if receiver clock speed is deviated	20
2.4.2	In full duplex mode, the Parity Error (PE) flag can be cleared by writing the data register	20
2.4.3	Parity Error (PE) flag is not set when receiving in Mute mode using address mark detection	20
2.4.4	Break frame is transmitted regardless of nCTS input line status	20
2.4.5	nRTS signal abnormally driven low after a protocol violation	21
2.4.6	Start bit detected too soon when sampling for NACK signal from the smartcard	21
2.4.7	Break request can prevent the Transmission Complete flag (TC) from being set	22
2.4.8	Guard time is not respected when data are sent on TXE events	22
2.4.9	nRTS is active while RE or UE = 0	22
2.5	USB peripheral limitation	23
2.5.1	Pull-up resistor has a value lower than 1.5 kOhm	23
2.6	SPI peripheral limitations	23
2.6.1	CRC still sensitive to communication clock when SPI is in slave mode even with NSS high	23
2.6.2	BSY bit may stay high at the end of a data transfer in Slave mode	24
2.6.3	Wrong CRC calculation when the polynomial is even	24
2.6.4	Wrong CRC transmitted in Master mode with delayed SCK feedback	25
2.6.5	SPI CRC may be corrupted when a peripheral connected to the same DMA channel of the SPI finishes its DMA transaction	25
2.6.6	Corrupted last bit of data and/or CRC, received in Master mode with delayed SCK feedback	26
2.7	I2S peripheral limitations	27
2.7.1	In I2S Slave mode, WS level must be set by the external master when enabling the I2S	27
2.7.2	Corrupted last bit of data and/or CRC, received in Master mode with delayed SCK feedback	27
2.8	ADC peripheral limitations	27
2.8.1	ADC converter partially tested on parts with date code before 047	27
2.9	DAC peripheral limitations	28

2.9.1	Spurious activation of DAC output buffer (PA4 and PA5)	28
2.10	RTC limitation	28
2.10.1	Spurious tamper detection when disabling the tamper channel	28
2.10.2	RTC calendar registers are not locked properly	28
2.11	Package limitation	29
2.11.1	Thermal characteristics for UFQFPN48 package	29
3	Revision history	30

List of tables

Table 1.	Device summary	1
Table 2.	Device identification	1
Table 3.	Cortex®-M3 core limitations and impact on microcontroller behavior	6
Table 4.	Summary of silicon limitations	9
Table 5.	Maximum allowable APB frequency at 30 pF load	26
Table 6.	Document revision history	30

1 ARM® 32-bit Cortex®-M3 limitations

An ARM errata notice of the STM32L1xxxx core is available searching “Cortex®-M3 errata” at the following web address: www.arm.com.

All the described limitations are minor and relate to revision r2p0-00rel0 of the Cortex®-M3 core. [Table 3](#) summarizes these limitations and their implications on the behavior of the STM32L1xxxx ultra-low-power devices.

Table 3. Cortex®-M3 core limitations and impact on microcontroller behavior

ARM ID	ARM category	ARM summary of errata	Impact on STM32L1xxxx ultra-low-power devices
752419	Cat 2	Interrupted loads to SP can cause erroneous behavior	Minor
740455	Cat 2	SVC and BusFault/MemManage may occur out of order	Minor
602117	Cat 2	LDRD with base in list may result in incorrect base register when interrupted or faulted	Minor
563915	Cat 2	Event register is not set by interrupts and debug	Minor

1.1 Cortex®-M3 limitation description for the STM32L1xxxx ultra-low-power devices

Only the limitations described below have an impact, even though minor, on the implementation of the STM32L1xxxx ultra-low-power devices.

All other limitations described in the ARM errata notice (and summarized in [Table 3](#) above) have no impact and are not related to the implementation of the STM32L1xxxx ultra-low-power devices (Cortex-M3 r2p0-00rel0).

1.1.1 Cortex®-M3 LDRD with base in list may result in incorrect base register when interrupted or faulted

Description

The Cortex®-M3 Core has a limitation when executing an LDRD instruction from the system-bus area, with the base register in a list of the form LDRD Ra, Rb, [Ra, #imm]. The execution may not complete after loading the first destination register due to an interrupt before the second loading completes or due to the second loading getting a bus fault.

Workarounds

1. This limitation does not impact the device code execution when executing from the embedded Flash memory, which is the standard use of the microcontroller.
2. Use the latest compiler releases. As of today, the compilers no longer generate this particular sequence. Moreover, a scanning tool is provided to detect this sequence on previous releases (refer to your preferred compiler provider).

1.1.2 Cortex®-M3 event register is not set by interrupts and debug

Description

When interrupts related to a wake from event (WFE) occur before the WFE is executed, the event register used for WFE wakeup events is not set and the event is missed. Therefore, when the WFE is executed, the core does not wake up from a WFE if no other event or interrupt occurs.

Workarounds

1. For the following interrupt sources:
 - All external interrupts/events lines (EXTI)
 - PVD output on EXTI line 16 (if VREFINT is enabled only)
 - RTC Alarm on EXTI line 17
 - USB Wake-up on EXTI line 18
 - RTC tamper and timestamp on EXTI line 19
 - RTC Wake-up on EXTI line 20
 - Comparator 1 wake-up on EXTI line 21 (if VREFINT is enabled only)
 - Comparator 2 wake-up on EXTI line 22 (if VREFINT is enabled only)

Use STM32L1xxx external events instead of interrupts to wake up the core from a WFE by configuring an external or internal EXTI line in event mode.

2. For all other interrupt sources, a timer must be programmed to provide a timeout event and wake-up the core if the event is likely to arrive before the WFE instruction is executed.

1.1.3 Cortex®-M3 interrupted loads to the stack-pointer can cause erroneous behavior

Description

If an interrupt occurs during the data-phase of a single word load to the stack-pointer (SP/R13), an erroneous behaviour can occur. In all cases, returning from the interrupt will result in the load instruction being executed in an additional time. For all instructions performing an update to the base register, the base register will be erroneously updated on each execution, resulting in the stack-pointer being loaded from an incorrect memory location.

The instructions affected by this limitation are the following:

- LDR SP, [Rn],#imm
- LDR SP, [Rn,#imm]!
- LDR SP, [Rn,#imm]
- LDR SP, [Rn]
- LDR SP, [Rn,Rm]

Workaround

As of today, no compiler generates these particular instructions. This limitation can only occur with hand-written assembly code.

Both issues can be solved by replacing the direct load to the stack pointer by an intermediate load to a general-purpose register followed by a move to the stack pointer.

Example:

Replace LDR SP, [R0] by

```
LDR R2,[R0]
```

```
MOV SP,R2
```

1.1.4 **SVC and BusFault/MemManage may occur out of order**

Description

If an SVC exception is generated by executing the SVC instruction while the following instruction fetch is faulted, then the MemManage or BusFault handler may be entered even though the faulted instruction which followed the SVC should not have been executed.

Workaround

A work around is only required if the SVC handler will not return to the return address that has been stacked for the SVC exception and the instruction access after the SVC will fault. If this is the case then padding can be inserted between the SVC and the faulting area of code, for example, by inserting NOP instructions.

2 STM32L1xxx6/8/B device silicon limitations

[Table 4](#) gives a summary of the fix status.

The legend for [Table 4](#) is as follows:

- A = workaround available,
- N = no workaround available,
- P = partial workaround available
- '-' and grayed = fixed.

Table 4. Summary of silicon limitations

Links to silicon limitations		Rev Y (cut 1.1)	Rev X (cut 1.2)	Rev W (cut 1.3)	Rev V (cut 1.5)
Section 2.1: System limitations	Section 2.1.1: Unexpected Flash/EEPROM behavior on system reset during programming/erasing	N	-	-	-
	Section 2.1.2: Bootloader unavailability	N	-	-	-
	Section 2.1.3: Undefined instruction exception during IAP	A	-	-	-
	Section 2.1.4: Factory trimming values not available	A	A	A	-
	Section 2.1.5: Debug support for low-power modes with entry through the WFE instruction	A	A	A	A
	Section 2.1.6: Operating temperature range limited to “-10°C to +85°C”	N	N	-	-
	Section 2.1.7: MCU may not restart after a reset when using HSE bypass as main clock source	N	N	-	-
	Section 2.1.8: Pull-up on PB7 when configured in analog mode	A	A	A	A
	Section 2.1.9: Range 1 of dynamic voltage scaling has a limit lower than 2.0 V	A	A	A	-
	Section 2.1.10: HSEBYP bit of Clock control register has an undefined reset value	-	-	A	A
	Section 2.1.11: Delay after enabling an RCC peripheral clock	A	A	A	A
	Section 2.1.12: Flash memory wakeup issue when waking up from Stop or Sleep with Flash memory in power-down mode	A	A	A	A
	Section 2.1.13: Unexpected system reset when waking up from Stop mode with regulator in low-power mode	A	A	A	A
Section 2.2: IWDG peripheral limitation	Section 2.2.1: RVU and PVU flags are not reset in Stop mode	A	A	A	A

Table 4. Summary of silicon limitations (continued)

Links to silicon limitations		Rev Y (cut 1.1)	Rev X (cut 1.2)	Rev W (cut 1.3)	Rev V (cut 1.5)
Section 2.3: I2C peripheral limitations	Section 2.3.1: SMBus standard not fully supported	A	A	A	A
	Section 2.3.2: Wrong behavior of I2C peripheral in Master mode after misplaced STOP	A	A	A	A
	Section 2.3.3: Violation of I2C "setup time for repeated START condition" parameter	A	A	A	A
	Section 2.3.4: In I2C slave "NOSTRETCH" mode, underrun errors may not be detected and may generate bus errors	A	A	A	A
	Section 2.3.5: Spurious bus error detection in Master mode	A	A	A	A
	Section 2.3.6: 10-bit Master mode: new transfer cannot be launched if first part of the address has not been acknowledged by the slave	A	A	A	A
Section 2.4: USART peripheral limitations	Section 2.4.1: Idle frame is not detected if receiver clock speed is deviated	N	N	N	N
	Section 2.4.2: In full duplex mode, the Parity Error (PE) flag can be cleared by writing the data register	A	A	A	A
	Section 2.4.3: Parity Error (PE) flag is not set when receiving in Mute mode using address mark detection	N	N	N	N
	Section 2.4.4: Break frame is transmitted regardless of nCTS input line status	N	N	N	N
	Section 2.4.5: nRTS signal abnormally driven low after a protocol violation	A	A	A	A
	Section 2.4.6: Start bit detected too soon when sampling for NACK signal from the smartcard	N	N	N	N
	Section 2.4.7: Break request can prevent the Transmission Complete flag (TC) from being set	A	A	A	A
	Section 2.4.8: Guard time is not respected when data are sent on TXE events	A	A	A	A
	Section 2.4.9: nRTS is active while RE or UE = 0	A	A	A	A
Section 2.5: USB peripheral limitation	Section 2.5.1: Pull-up resistor has a value lower than 1.5 kOhm	A	A	A	A

Table 4. Summary of silicon limitations (continued)

Links to silicon limitations		Rev Y (cut 1.1)	Rev X (cut 1.2)	Rev W (cut 1.3)	Rev V (cut 1.5)
Section 2.6: SPI peripheral limitations	Section 2.6.1: CRC still sensitive to communication clock when SPI is in slave mode even with NSS high	A	A	A	A
	Section 2.6.2: BSY bit may stay high at the end of a data transfer in Slave mode	A	A	A	A
	Section 2.6.3: Wrong CRC calculation when the polynomial is even	A	A	A	A
	Section 2.6.4: Wrong CRC transmitted in Master mode with delayed SCK feedback	A	A	A	A
	Section 2.6.5: SPI CRC may be corrupted when a peripheral connected to the same DMA channel of the SPI finishes its DMA transaction	N	N	N	N
	Section 2.6.6: Corrupted last bit of data and/or CRC, received in Master mode with delayed SCK feedback	A	A	A	A
Section 2.7: I2S peripheral limitations	Section 2.7.1: In I2S Slave mode, WS level must be set by the external master when enabling the I2S	A	A	A	A
	Section 2.7.2: Corrupted last bit of data and/or CRC, received in Master mode with delayed SCK feedback	A	A	A	A
Section 2.8: ADC peripheral limitations	Section 2.8.1: ADC converter partially tested on parts with date code before 047	A	-	-	-
Section 2.9: DAC peripheral limitations	Section 2.9.1: Spurious activation of DAC output buffer (PA4 and PA5)	A	A	A	A
Section 2.10: RTC limitation	Section 2.10.1: Spurious tamper detection when disabling the tamper channel	N	N	N	N
	Section 2.10.2: RTC calendar registers are not locked properly	A	A	A	A
Section 2.11: Package limitation	Section 2.11.1: Thermal characteristics for UFQFPN48 package	A	A	A	A

2.1 System limitations

2.1.1 Unexpected Flash/EEPROM behavior on system reset during programming/erasing

Description

Part of the internal EEPROM state machine is not correctly reset if the reset occurs during a programming or reset phase. This can cause the MCU either to take several seconds to exit from the reset phase or need a power cycling to resume operation.

Workaround

None.

2.1.2 Bootloader unavailability

Description

The boot loader cannot be used due the issue described in [Section 2.1.3: Undefined instruction exception during IAP](#).

Workaround

No workaround is available.

2.1.3 Undefined instruction exception during IAP

Description

The Flash memory can return a corrupted data following a programming of the Flash itself or the EEPROM area and possibly cause a hard fault exception due to undefined instruction.

The behavior depends on the location of the routine which is executing the programming. It occurs only when IAP is executed from the upper part of memory (0x08000000 to 0x0800 FFFF).

The issue can occur when the bootloader is used.

Workaround

There are two possible workarounds

1. The IAP routines must be located in the bottom part of the memory (0x08010000 to 0x0801 FFFF).

or

2. The IAP routine must be relocated in RAM, and programming followed by a dummy read in Flash before resuming execution from the Flash memory.

Before branching to the RAM, the following procedure must be followed:

The vector table and all exception and interrupt handlers that might be triggered must be copied into the RAM memory. The vector table offset must be updated in the SCB_VTOR register of the Cortex-M3.

The amount of RAM memory needed can be minimized by disabling all interrupts during the IAP execution. This can be done with the void `__disable_irq(void)` function from the CMSIS library. Similarly, the Clock Security System (CSS) can be disabled to prevent any NMI from occurring. However, it is mandatory to remap at least the Cortex M3's fault handlers.

2.1.4 Factory trimming values not available

Description

The following parameters are not available or wrong in the non-volatile memory factory trimming area:

- V_{REFINT} value
- Temperature sensor value at 90 °C

Workaround

Parameters can be measured on the customer production line and stored in the data EEPROM.

2.1.5 Debug support for low-power modes with entry through the WFE instruction

Description

The `DBG_STOP` and `DBG_SLEEP` bits in the `DBGMCU_CR` register can be used to debug an application low-power mode without losing the JTAG connection.

The application may not resume correctly in the following cases:

- the `DBG_STOP` bit is set and the WFE instruction is used.
- the `DBG_SLEEP` bit is set, either the `SRAMLPEN` or the `FLTFEN` bits are set (in the `RCC_AHBLPENR` register) and the WFE instruction is used.

This affects only the debug of Stop mode and Sleep modes with an entry into WFE mode. Low-power modes are not affected when the MCU is not in debug configuration.

Workaround

The WFE instruction must be executed in a dedicated function with 1 instruction (NOP) between the execution of the WFE and the BX LR.

```
__asm void _WFE(void)
{
  WFE
  NOP
  BX LR
}
```

2.1.6 Operating temperature range limited to “-10°C to +85°C”

Description

The microcontroller has an operating temperature range of -10°C to +85°C.

Workaround

None.

2.1.7 MCU may not restart after a reset when using HSE bypass as main clock source

Description

When the system clock source is the HSE bypass (for instance, external oscillator), the MCU may not restart after a reset event.

Workaround

None.

2.1.8 Pull-up on PB7 when configured in analog mode

Description

PB7 can be used as a Power Voltage Detection Input. To select this, the IO is configured in analog mode through GPIOB_MODER and selected as external input analog voltage for the PVD level selection through bits PLS[2:0] in the PWR_CR register.

When PB7 is configured in analog mode but not selected for the PVD level selection, then an internal pull-up is visible through PB7.

Workaround

Configuring PB7 to limit the power consumption whatever the external connection can be done differently:

1. Keep PB7 in Input mode (default of GPIOB_MODER)
2. Disconnect the schmidt trigger on PB7 by programming the RI_HYSCR1.

2.1.9 Range 1 of dynamic voltage scaling has a limit lower than 2.0 V

Description

In latest documents, the range 1 of dynamic voltage scaling is available from $V_{DD} = 1.71$ V and above. This does not apply to all revisions.

Workaround

The revisions impacted by this limitation can use range 1 when V_{DD} is equal to or above 2.0 V.

2.1.10 HSEBYP bit of Clock control register has an undefined reset value

Description

The HSEBYP bit, which bypasses the oscillator with an external clock, is not reset after system reset nor after power-on reset. After power-on reset, it has an undefined value.

Workaround

The software has to set the HSEBYP bit to the requested value after reset.

2.1.11 Delay after enabling an RCC peripheral clock

Description

When enabling an RCC peripheral clock, there is a delay between the clock enable and the effective peripheral enabling. The user should take this into account to manage the peripheral read/write to registers.

This delay depends on the peripheral mapping:

- If the peripheral is mapped on AHB: the delay should be equal to 2 AHB cycles.
- If the peripheral is mapped on APB: the delay should be equal to 1 + (AHB/APB prescaler) cycles.

Workaround

There are two workarounds:

1. Use the DSB instruction to stall the Cortex-M CPU pipeline until the instruction is completed.
2. Insert "n" NOPs between the RCC enable bit write and the peripheral register writes (n = 2 for AHB peripherals, n = 1 + AHB/APB prescaler in case of APB peripherals).

2.1.12 Flash memory wakeup issue when waking up from Stop or Sleep with Flash memory in power-down mode

Description

When an external wakeup event (EXTI) occurs in a narrow time window around low-power mode entry (Stop or Sleep mode with Flash memory in power-down state), the Flash wakeup time may be increased. As a result, the first data read or instruction fetch from the Flash memory may be incorrect.

The probability that this issue occurs is very low since it may happen only during a very narrow time window.

Workarounds

Two workarounds are available:

- Do not put the Flash memory module in power-down mode when entering Sleep or Low-power sleep modes.
- Before entering Stop mode by executing a WFI instruction from RAM, set the RUN_PD bit in the FLASH_ACR register. After exiting from Stop mode, the Flash memory is automatically powered ON and the user can resume program execution from Flash memory. After wakeup, clear the RUN_PD bit.

2.1.13 Unexpected system reset when waking up from Stop mode with regulator in low-power mode

Description

If the device returns to Run mode after waking up from Stop mode while the internal voltage regulator is configured to switch to low-power mode in Stop mode (LPSSDR=1 in PWR_CR register), an unexpected system reset may occur if the following conditions are met:

- The internal regulator is set to Range 2 or Range 3 before entering Stop mode.
- V_{DD} power supply is below 2.7 V.

The probability that this issue occurs is very low since it may happen only for very narrow supply voltage windows which vary from one device to another.

This reset is internal only and does not affect the NRST pin state and the flags in the control/status register (RCC_CSR).

Workarounds

Two workarounds are possible:

- Enter Stop mode with the internal voltage regulator set to main mode (LPSSDR=0 in PWR_CR).
- Set the internal voltage regulator to Range1 before entering Stop mode.

2.2 IWDG peripheral limitation

2.2.1 RVU and PVU flags are not reset in Stop mode

Description

The RVU and PVU flags of the IWDG_SR register are set by hardware after a write access to the IWDG_RLR and the IWDG_PR registers, respectively. If the Stop mode is entered immediately after the write access, the RVU and PVU flags are not reset by hardware.

Before performing a second write operation to the IWDG_RLR or the IWDG_PR register, the application software must wait for the RVU or PVU flag to be reset. However, since the RVU/PVU bit is not reset after exiting Stop mode, the software goes into an infinite loop and the independent watchdog (IWDG) generates a reset after the programmed timeout period.

Workaround

Wait until the RVU or PVU flag of the IWDG_SR register are reset before entering Stop mode.

2.3 I²C peripheral limitations

2.3.1 SMBus standard not fully supported

Description

The I²C peripheral is not fully compliant with the SMBus v2.0 standard since it does not support the capability to NACK an invalid byte/command.

Workarounds

The following higher-level mechanisms should be used to verify that a write operation is being performed correctly at the target device:

1. The SMBA pin if supported by the host
2. The alert response address (ARA) protocol
3. The host notify protocol

2.3.2 Wrong behavior of I²C peripheral in Master mode after misplaced STOP

Description

The I²C peripheral does not enter Master mode properly if a misplaced STOP is generated on the bus. This can happen in the following conditions:

- If a void message is received (START condition immediately followed by a STOP): the BERR (bus error) flag is not set, and the I²C peripheral is not able to send a START condition on the bus after writing to the START bit in the I2C_CR2 register.
- In the other cases of a misplaced STOP, the BERR flag is set in the IC2_CR2 register. If the START bit is already set in I2C_CR2, the START condition is not correctly generated on the bus and can create bus errors.

Workaround

In the I²C standard, it is not allowed to send a STOP before the full byte is transmitted (8 bits + acknowledge). Other derived protocols like CBUS allow it, but they are not supported by the I²C peripheral.

In case of noisy environment in which unwanted bus errors can occur, it is recommended to implement a timeout to ensure that the SB (start bit) flag is set after the START control bit is set. In case the timeout has elapsed, the peripheral must be reset by setting the SWRST bit in the I2C_CR2 control register. The I²C peripheral should be reset in the same way if a BERR is detected while the START bit is set in I2C_CR2.

No fix is planned for this limitation.

2.3.3 Violation of I²C “setup time for repeated START condition” parameter

Description

In case of a repeated Start, the “setup time for repeated START condition” parameter (named $t_{SU(STA)}$ in the datasheet and $Tsu:sta$ in the I²C specifications) may be slightly violated when the I²C operates in Master Standard mode at a frequency ranging from 88 to 100 kHz. $t_{SU(STA)}$ minimum value may be 4 μ s instead of 4.7 μ s.

The issue occurs under the following conditions:

1. The I²C peripheral operates in Master Standard mode at a frequency ranging from 88 to 100 kHz (no issue in Fast mode).
2. and the SCL rise time meets one of the following conditions:
 - The slave does not stretch the clock and the SCL rise time is more than 300 ns (the issue cannot occur when the SCL rise time is less than 300 ns).
 - or the slave stretches the clock.

Workaround

Reduce the frequency down to 88 kHz or use the I²C Fast mode if it is supported by the slave.

2.3.4 In I²C slave “NOSTRETCH” mode, underrun errors may not be detected and may generate bus errors

Description

The data valid time ($t_{VD;DAT}$, $t_{VD;ACK}$) described by the I²C specifications may be violated as well as the maximum current data hold time ($t_{HD;DAT}$) under the conditions described below. In addition, if the data register is written too late and close to the SCL rising edge, an error may be generated on the bus: SDA toggles while SCL is high. These violations cannot be detected because the OVR flag is not set (no transmit buffer underrun is detected).

This issue occurs under the following conditions:

1. The I²C peripheral operates In Slave transmit mode with clock stretching disabled (NOSTRETCH=1).
2. and the application is late to write the DR data register, but not late enough to set the OVR flag (the data register is written before the SCL rising edge).

Workaround

If the master device supports it, use the clock stretching mechanism by programming the bit NOSTRETCH=0 in the I2C_CR1 register.

If the master device does not support it, ensure that the write operation to the data register is performed just after TXE or ADDR events. The user can use an interrupt on the TXE or ADDR flag and boost its priority to the higher level or use DMA.

Using the “NOSTRETCH” mode with a slow I²C bus speed can prevent the application from being late to write the DR register (second condition).

Note: The first data to be transmitted must be written into the data register after the ADDR flag is cleared, and before the next SCL rising edge, so that the time window to write the first data into the data register is less than t_{LOW} .

If this is not possible, a possible workaround can be the following:

1. Clear the ADDR flag
2. Wait for the OVR flag to be set
3. Clear OVR and write the first data.

The time window for writing the next data is then the time to transfer one byte. In that case, the master must discard the first received data.

2.3.5 Spurious bus error detection in Master mode

Description

In Master mode, a bus error can be detected by mistake, so the BERR flag can be wrongly raised in the status register. This will generate a spurious bus error interrupt if the interrupt is enabled. A bus error detection has no effect on the transfer in Master mode, therefore the I2C transfer can continue normally.

Workaround

If a bus error interrupt is generated in Master mode, the BERR flag must be cleared by software. No other action is required and the on-going transfer can be handled normally.

2.3.6 10-bit Master mode: new transfer cannot be launched if first part of the address has not been acknowledged by the slave

Description

In Master mode, the master automatically sends a STOP bit when the slave has not acknowledged a byte during the address transmission.

In the 10-bit addressing mode, if the first part of the 10-bit address (corresponding to 10-bit header + 2 MSB) has not been acknowledged by the slave, the STOP bit is sent but the START bit is not cleared and the master cannot launch a new transfer.

Workaround

When the I2C is configured in 10-bit addressing Master mode and the NACKF status flag is set in the I2C_ISR register while the START bit is still set in the I2C_CR2 register, then proceed as follows:

1. Wait for the STOP condition detection (STOPF = 1 in I2C_ISR register).
2. Disable the I2C peripheral.
3. Wait for a minimum of 3 APB cycles.
4. Enable the I2C peripheral again.

2.4 USART peripheral limitations

2.4.1 Idle frame is not detected if receiver clock speed is deviated

Description

If the USART receives an idle frame followed by a character, and the clock of the transmitter device is faster than the USART receiver clock, the USART receive signal falls too early when receiving the character start bit, with the result that the idle frame is not detected (IDLE flag is not set).

Workaround

None.

2.4.2 In full duplex mode, the Parity Error (PE) flag can be cleared by writing the data register

Description

In full duplex mode, when the Parity Error flag is set by the receiver at the end of a reception, it may be cleared while transmitting by reading the USART_SR register to check the TXE or TC flags and writing data in the data register.

Consequently, the software receiver can read the PE flag as '0' even if a parity error occurred.

Workaround

The Parity Error flag should be checked after the end of reception and before transmission.

2.4.3 Parity Error (PE) flag is not set when receiving in Mute mode using address mark detection

Description

The USART receiver is in Mute mode and is configured to exit the Mute mode using the address mark detection. When the USART receiver recognizes a valid address with a parity error, it exits the Mute mode without setting the Parity Error flag.

Workaround

None.

2.4.4 Break frame is transmitted regardless of nCTS input line status

Description

When CTS hardware flow control is enabled (CTSE = 1) and the Send Break bit (SBK) is set, the transmitter sends a break frame at the end of current transmission regardless of nCTS input line status.

Consequently, if an external receiver device is not ready to accept a frame, the transmitted break frame is lost.

Workaround

None.

2.4.5 nRTS signal abnormally driven low after a protocol violation**Description**

When RTS hardware flow control is enabled, the nRTS signal goes high when a data is received. If this data was not read and a new data is sent to the USART (protocol violation), the nRTS signal goes back to low level at the end of this new data.

Consequently, the sender gets the wrong information that the USART is ready to receive further data.

On USART side, an overrun is detected which indicates that some data has been lost.

Workaround

Workarounds are required only if the other USART device violates the communication protocol which is not the case in most applications.

Two workarounds can be used:

- After data reception and before reading in the data in the data register, the software takes over the control of the nRTS signal as a GPIO and holds it high as long as needed. If the USART device is not ready, the software holds the nRTS pin high, and releases it when the device is ready to receive new data.
- The time required by the software to read the received data must always be lower than the duration of the second data reception. For example, this can be ensured by treating all the receptions by DMA mode.

2.4.6 Start bit detected too soon when sampling for NACK signal from the smartcard**Description**

In the ISO7816, when a character parity error is incorrect, the smartcard receiver shall transmit a NACK error signal at (10.5 ± 0.2) etu after the character Start bit falling edge. In this case, the USART transmitter should be able to detect correctly the NACK signal by sampling at (11.0 ± 0.2) etu after the character Start bit falling edge.

The USART peripheral used in smartcard mode doesn't respect the (11 ± 0.2) etu timing, and when the NACK falling edge arrives at 10.68 etu or later, the USART might misinterpret this transition as a Start bit even if the NACK is correctly detected.

Workaround

None.

2.4.7 Break request can prevent the Transmission Complete flag (TC) from being set

Description

After the end of transmission of a data (D1), the Transmission Complete (TC) flag will not be set in the following conditions:

- CTS hardware flow control is enabled.
- D1 is being transmitted.
- A break transfer is requested before the end of D1 transfer.
- nCTS is de-asserted before the end of transfer of D1.

Workaround

If the application needs to detect the end of transfer of the data, the break request should be done after making sure that the TC flag is set.

2.4.8 Guard time is not respected when data are sent on TXE events

Description

In smartcard mode, when sending a data on TXE event, the programmed guard time is not respected i.e. the data written in the data register is transferred on the bus without waiting for the completion of the guardtime duration corresponding to the previous transmitted data.

Workaround

Write the data after TC is set because in smartcard mode, the TC flag is set at the end of the guard time duration.

2.4.9 nRTS is active while RE or UE = 0

Description

The nRTS line is driven low as soon as RTSE bit is set even if the USART is disabled (UE = 0) or the receiver is disabled (RE = 0) i.e. not ready to receive data.

Workaround

Configure the I/O used for nRTS as alternate function after setting the UE and RE bits.

2.5 USB peripheral limitation

2.5.1 Pull-up resistor has a value lower than 1.5 kOhm

Description

The pull-up resistor on USB line is requested to have a nominal value of 1.5 k Ω , whereas the characterization of the internal pull-up shows a value between 0.81 k Ω and 0.95 k Ω on the full temperature range.

Workaround

An external pull-up resistor controlled by a GPIO can be used.

2.6 SPI peripheral limitations

2.6.1 CRC still sensitive to communication clock when SPI is in slave mode even with NSS high

Description

When the SPI is configured in slave mode with the CRC feature enabled, the CRC is calculated even if the NSS pin deselected the SPI (high level applied on the NSS pin).

Workaround

The CRC has to be cleared on both Master and Slave sides between the slave deselection (high level on NSS) and the slave selection (low level on NSS), in order to resynchronize the master and slave for their respective CRC calculation.

The procedure to clear the CRC is as follows:

1. Disable the SPI (SPE = 0)
2. Clear the CRCEN bit
3. Set the CRCEN bit
4. Enable the SPI (SPE = 1)

2.6.2 BSY bit may stay high at the end of a data transfer in Slave mode

Description

The BSY flag may sporadically remain high at the end of a data transfer in Slave mode. The issue appears when an accidental synchronization happens between the internal CPU clock and external SCK clock provided by the master.

This is related to the end of data transfer detection while the SPI is enabled in Slave mode.

As a consequence, the end of data transaction may be not recognized when the software needs to monitor it (e.g. at the end of session before entering the low-power mode or before direction of data line has to be changed at half duplex bidirectional mode). The BSY flag is unreliable to detect the end of any data sequence transaction.

Workaround

When the NSS hardware management is applied and the NSS signal is provided by the master, the end of a transaction can be detected by the NSS polling by the slave.

- If the SPI receiving mode is enabled, the end of a transaction with the master can be detected by the corresponding RXNE event signaling the last data transfer completion.
- In SPI transmit mode, the user can check the BSY under timeout corresponding to the time necessary to complete the last data frame transaction. The timeout should be measured from TXE event signaling the last data frame transaction start (it is raised once the second bit transaction is ongoing). Either BSY becomes low normally or the timeout expires when the synchronization issue happens.

When upper workarounds are not applicable, the following sequence can be used to prevent the synchronization issue at SPI transmit mode.

1. Write last data to data register
2. Poll TXE until it becomes high to ensure the data transfer has started
3. Disable SPI by clearing SPE while the last data transfer is still ongoing
4. Poll the BSY bit until it becomes low
5. The BSY flag works correctly and can be used to recognize the end of the transaction.

Note: This workaround can be used only when CPU has enough performance to disable SPI after the TXE event is detected while the data frame transfer is still ongoing. It is impossible to achieve it when the ratio between CPU and SPI clock is low and the data frame is short especially. In this specific case the timeout can be measured from TXE, while calculating a fixed number of CPU clock periods corresponding to the time necessary to complete the data frame transaction.

2.6.3 Wrong CRC calculation when the polynomial is even

Description

When the CRC is enabled, the CRC calculation will be wrong if the polynomial is even.

Workaround

Use odd polynomial.

2.6.4 Wrong CRC transmitted in Master mode with delayed SCK feedback

Description

In transmit transaction of the SPI interface in Master mode with the CRC enabled, the CRC data transmission may be corrupted if the delay of an internal feedback signal derived from the SCK output (further feedback clock) is greater than two APB clock periods. While the data and the CRC bit shifting and the transfer is based on an internal clock, the CRC progressive calculation uses the feedback clock. If the delay of the feedback clock is greater than two APB periods, the transmitted CRC value may get wrong.

The main factors contributing to the delay increase are low V_{DD} level, high temperature, high SCK pin capacitive load and low SCK I/O output speed. The SPI communication speed has no impact.

Workaround

The following workaround can be adopted, jointly or individually:

- Decrease the APB clock speed.
- Configure the IO pad of the SCK pin to be faster.

[Table 5](#) gives the maximum allowable APB frequency versus the GPIOx_OSPEEDR output speed control field setting for the SCK pin, at 30 pF of capacitive load.

2.6.5 SPI CRC may be corrupted when a peripheral connected to the same DMA channel of the SPI finishes its DMA transaction

Description

When the SPI is running with the CRC feature enabled at all the modes, the CRC calculation may be frozen and checked corrupted before the CRCNEXT bit is written. It can happen if a peripheral, mapped on the same DMA channel than the SPI, is doing a DMA transfer whereas the SPI is configured to manage data transfers by software (IT or polling). As a consequence the CRC error flag is unduly raised.

Workaround

There is no known workaround of this conflict. If possible use the DMA for SPI transfers to avoid this conflict.

2.6.6 Corrupted last bit of data and/or CRC, received in Master mode with delayed SCK feedback

Description

In receive transaction, in both I²S and SPI Master modes, the last bit of the transacted frame is not captured when the signal provided by internal feedback loop from the SCK pin exceeds a critical delay. The lastly transacted bit of the stored data then keeps the value from the pattern received previously. As a consequence, the last receive data bit may be wrong and/or the CRCERR flag can be unduly asserted in the SPI mode if any data under check sum and/or just the CRC pattern is wrongly captured.

In SPI mode, data are synchronous with the APB clock. A delay of up to two APB clock periods can thus be tolerated for the internal feedback delay. The I2S mode is more sensitive than the SPI mode since the SCK clock is not synchronized with the APB clock. In this case, the margin of the internal feedback delay is lower than one APB clock period.

The main factors contributing to the delay increase are low V_{DD} level, high temperature, high SCK pin capacitive load and low SCK I/O output speed. The SPI communication speed has no impact.

Workarounds

The following workaround can be adopted, jointly or individually:

- Decrease the APB clock speed.
- Configure the IO pad of the SCK pin to be faster.

[Table 5](#) gives the maximum APB frequency versus the GPIOx_OSPEEDR output speed control field setting for the SCK pin, at 30 pF of capacitive load.

Table 5. Maximum allowable APB frequency at 30 pF load

Setting of OSPEEDR bits [1:0] for the SCK pin	Maximum APB frequency for SPI [MHz]	Maximum APB frequency for I2S [MHz]
Very high (11)	32	32
High (10)	28 (30 if VDD > 1.8 V)	28 (30 if VDD > 1.8 V)
Medium (01)	11 (13 if VDD > 1.8 V)	8 (9 if VDD > 1.8 V)
Low (00)	2	1.5

2.7 I2S peripheral limitations

2.7.1 In I2S Slave mode, WS level must be set by the external master when enabling the I2S

Description

In Slave mode, the WS signal level is used only to start the communication. If the I2S (in Slave mode) is enabled while the master is already sending the clock and the WS signal level is low (for I2S protocol) or is high (for the LSB or MSB-justified mode), the slave starts communicating data immediately. In this case, the master and the slave will be desynchronized throughout the whole communication.

Workaround

The I2S peripheral must be enabled when the external master sets the WS line at:

- High level when the I2S protocol is selected.
- Low level when the LSB or MSB-justified mode is selected.

2.7.2 Corrupted last bit of data and/or CRC, received in Master mode with delayed SCK feedback

The limitation described in [Section 2.6.6: Corrupted last bit of data and/or CRC, received in Master mode with delayed SCK feedback](#) also applies to I2S interface.

2.8 ADC peripheral limitations

2.8.1 ADC converter partially tested on parts with date code before 047

Description

The ADC converter production test is partially implemented for parts with date code before 047. As a result, it must be anticipated that 0.15% of parts will have ADC failures.

Workaround

None.

2.9 DAC peripheral limitations

2.9.1 Spurious activation of DAC output buffer (PA4 and PA5)

Description

The high speed signal with a falling edge and a slope higher than 7V/us can cause a spurious activation of the DAC buffer if applied on the pins PA4 and PA5. Such spurious activation can happen regardless of the GPIO configuration and it may pull a current from the signal source up to 1 mA in the typical conditions. As a result of this unintended DAC buffer pulling, a shape of the falling edge may change and cause shifted timing of the digital signal applied on the pin.

Workarounds

- Use another IO with an equivalent function.
- Reduce the slope of the signal applied on the affected pins.

2.10 RTC limitation

2.10.1 Spurious tamper detection when disabling the tamper channel

Description

If the tamper detection is configured for detection on the falling edge event (TAMPFLT=00 and TAMPxTRG=1) and if the tamper event detection is disabled when the tamper pin is at high level, a false tamper event is detected.

Workaround

None.

2.10.2 RTC calendar registers are not locked properly

Description

When reading the calendar registers with BYPSHAD=0, the RTC_TR and RTC_DR registers may not be locked after reading the RTC_SSR register. This happens if the read operation is initiated one APB clock period before the shadow registers are updated. This can result in a non-consistency of the three registers. Similarly, the RTC_DR register can be updated after reading the RTC_TR register instead of being locked.

Workaround

1. Use BYPSHAD = 1 mode (Bypass shadow registers), or
2. If BYPSHAD = 0, read SSR again after reading SSR/TR/DR to confirm that SSR is still the same, otherwise read the values again.

2.11 Package limitation

2.11.1 Thermal characteristics for UFQFPN48 package

Description

The thermal resistance junction-ambient for UFQFPN48 package was not correctly specified in STM32L15x6/8/B datasheet prior revision 8 and STM32L100x datasheet prior revision 2.

Workaround

Limit the power dissipation of the device to not exceed the maximum chip-junction temperature for the maximum ambient temperature at which the device is operated. For guidance and correct thermal resistance value, see the latest datasheet available on the company website.

3 Revision history

Table 6. Document revision history

Date	Revision	Changes
05-Jul-2010	1	Initial release.
01-Oct-2010	2	Added workarounds under Section 1.1.2: Cortex®-M3 event register is not set by interrupts and debug . Added Section 2.1: System limitations . Changed workaround under Section 2.4: Extra consumption in STOP / STANDBY mode . Added Section 2.2: IWDG peripheral limitation . Added Section 2.6: POR start-up delay at cold temperature .
06-Dec-2010	3	Removed sections describing Rev A issues fixed in Rev B. Added Section 2.1.3: Undefined instruction exception during IAP . Updated Section 2.1.4: Factory trimming values not available .
19-Jan-2011	4	Replaced Rev B by Rev Y. Modified descriptions of Section 2.3.2: Wrong behavior of I2C peripheral in Master mode after misplaced STOP , Section 2.3.3: Violation of I2C "setup time for repeated START condition" parameter and Section 2.3.4: In I2C slave "NOSTRETCH" mode, underrun errors may not be detected and may generate bus errors . Updated Table 4 .
25-Feb-2011	5	Added description of Rev W. Added Section 2.1.6: Debugging Stop mode with WFE entry and Section 2.1.7: MCU may not restart after a reset when using HSE bypass as main clock source .
12-Oct-2011	6	Updated Table 4 and Section 2.1.4: Factory trimming values not available . Added Section 2.3.5: Spurious bus error detection in Master mode and Section 2.5: USB peripheral limitation .
18-Dec-2012	7	Added rev V. Added Section 1.1.3: Cortex®-M3 interrupted loads to the stack-pointer can cause erroneous behavior and Section 1.1.4: SVC and BusFault/MemManage may occur out of order . Updated Table 2 . Updated Table 4 . Added Section 2.1.8: Pull-up on PB7 when configured in analog mode . USART limitation workaround update: Section 2.4.5: nRTS signal abnormally driven low after a protocol violation . IWDG PVU and RVU limitation update: Section 2.2: IWDG peripheral limitation . Replaced figure 2: LQFP100 top package view.

Table 6. Document revision history (continued)

Date	Revision	Changes
05-Nov-2013	8	Added: – Section 2.1.9: Range 1 of dynamic voltage scaling has a limit lower than 2.0 V – Section 2.1.10: HSEBYP bit of Clock control register has an undefined reset value – Section 2.1.11: Delay after enabling an RCC peripheral clock Updated Table 4: Summary of silicon limitations .
19-Feb-2014	9	Extended the document applicability to STM32L100x6/8/B devices. Updated Table 1: Device summary , Table 2: Device identification , Table 4: Summary of silicon limitations . Added Section 2.11: Package limitation . Added the Caution on the cover page.
10-Oct-2014	10	Added Section 2.6.2: BSY bit may stay high at the end of a data transfer in Slave mode .
07-Jul-2015	11	Removed appendix A section: all package markings put in the corresponding datasheets. Added USART limitations: - Section 2.4.6: Start bit detected too soon when sampling for NACK signal from the smartcard . - Section 2.4.7: Break request can prevent the Transmission Complete flag (TC) from being set . - Section 2.4.8: Guard time is not respected when data are sent on TXE events . - Section 2.4.9: nRTS is active while RE or UE = 0 . Added SPI limitation: - Section 2.6.3: Wrong CRC calculation when the polynomial is even . Added RTC limitation: - Section 2.10.1: Spurious tamper detection when disabling the tamper channel .
20-Aug-2015	12	Updated Table 4: Summary of silicon limitations : 'factory trimming values not available' system limitation is fixed for the Rev V. Added one I2C limitation: Section 2.3.5: Spurious bus error detection in Master mode . Updated Table 4: Summary of silicon limitations putting a workaround available status 'A' for the I2C limitation.

Table 6. Document revision history (continued)

Date	Revision	Changes
17-Nov-2015	13	Added system limitations: <ul style="list-style-type: none"> – <i>Section 2.1.12: Flash memory wakeup issue when waking up from Stop or Sleep with Flash memory in power-down mode.</i> – <i>Section 2.1.13: Unexpected system reset when waking up from Stop mode with regulator in low-power mode.</i>
07-Nov-2016	14	Added I ² C limitation: <ul style="list-style-type: none"> – <i>Section 2.3.6: 10-bit Master mode: new transfer cannot be launched if first part of the address has not been acknowledged by the slave.</i> Added RTC limitation: <ul style="list-style-type: none"> – <i>Section 2.10.2: RTC calendar registers are not locked properly.</i> Added DAC limitation: <ul style="list-style-type: none"> – <i>Section 2.9.1: Spurious activation of DAC output buffer (PA4 and PA5).</i> Added SPI limitations: <ul style="list-style-type: none"> – <i>Section 2.6.4: Wrong CRC transmitted in Master mode with delayed SCK feedback.</i> – <i>Section 2.6.5: SPI CRC may be corrupted when a peripheral connected to the same DMA channel of the SPI finishes its DMA transaction.</i> – <i>Section 2.6.6: Corrupted last bit of data and/or CRC, received in Master mode with delayed SCK feedback.</i> Added I2S limitations: <ul style="list-style-type: none"> – <i>Section 2.7.1: In I2S Slave mode, WS level must be set by the external master when enabling the I2S.</i> – <i>Section 2.7.2: Corrupted last bit of data and/or CRC, received in Master mode with delayed SCK feedback.</i>

IMPORTANT NOTICE – PLEASE READ CAREFULLY

STMicroelectronics NV and its subsidiaries ("ST") reserve the right to make changes, corrections, enhancements, modifications, and improvements to ST products and/or to this document at any time without notice. Purchasers should obtain the latest relevant information on ST products before placing orders. ST products are sold pursuant to ST's terms and conditions of sale in place at the time of order acknowledgement.

Purchasers are solely responsible for the choice, selection, and use of ST products and ST assumes no liability for application assistance or the design of Purchasers' products.

No license, express or implied, to any intellectual property right is granted by ST herein.

Resale of ST products with provisions different from the information set forth herein shall void any warranty granted by ST for such product.

ST and the ST logo are trademarks of ST. All other product or service names are the property of their respective owners.

Information in this document supersedes and replaces information previously supplied in any prior versions of this document.

© 2016 STMicroelectronics – All rights reserved