OK JONARDTOOLS ®

JIC-950C
Quick Clip Insertion Tool

(Used for terminating jumpers on Quick Clip 3 & 4 beam terminals)

Wire Cutter for
22 & 24 gauge wire

For jumper &
back-tap removal

Insertion Bit

DIRECTIONS:

1. Insert wire into hole at the top of the bit as shown
2. Bend wire over slot and down the side of the tool
3. Push tool straight into terminal
4. Withdraw tool